



SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING A FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREVENTING OR REDUCING THE LIKELIHOOD OF THIS TYPE OF PROBLEM. THEREFORE, CONDITIONS ARE REQUIRED THAT CANNOT BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER.

TITLE:  
 CATALOG:  
 DWG NO: CPS-4-4011-14-B1CS SIZE: C SHEET 1 OF 1

23171 Groesbeck Hwy.  
 Warren, MI 48089  
 P: (586) 774-6105 | F: (586) 774-5706  
 www.generalstructuresinc.com

**GENERAL STRUCTURES INC.**  
 A BIRMINGHAM COMPANY

3/17/2015  
 DRAWN: L. GRUNIS  
 CHECKED: \_\_\_\_\_  
 REVISION: \_\_\_\_\_ DATE: \_\_\_\_\_  
 APPROVED: \_\_\_\_\_  
 QUOTE: \_\_\_\_\_  
 S.O.# \_\_\_\_\_  
 REF: \_\_\_\_\_ SCALE: NONE

180°  
 270° 0° 90°  
 HANDHOLE